RAZER BLADE INTEL ME FIRMWARE UPDATER

This document is a step-by-step process on how to update the firmware of your Razer Blade laptop.

The update helps mitigate the associated effects of INTEL-SA-00213 vulnerability. According to Intel, this vulnerability may allow escalation of privilege, information disclosure, and/or denial of service of the user.

RELEASE NOTES

This updater will upgrade the system's Intel ME Firmware to address the potential issues caused by the INTEL-SA-00213 vulnerability.

BEFORE YOU START THE INSTALLATION PROCESS

1. Ensure that you have installed all the latest Microsoft® Windows Operating Systems and Security Updates. For help verifying your OS is up to date, refer to the following article from Microsoft.

https://support.microsoft.com/en-us/help/4027667/windows-update-windows-10

- 2. Ensure that your Blade is plugged into a wall outlet and not running on battery alone before proceeding.
- 3. Save any open documents on your computer and close all other programs before attempting this update.
- 4. Proceed to download the correct firmware below.

For Model Numbers with prefixes:

RZ09-02810 Razer Blade Stealth 13" (Early 2019)
RZ09-02812 Razer Blade Stealth 13" (Early 2019)

Download the firmware updater here: http://rzr.to/GgCRI

For Model Numbers with prefixes:

RZ09-03006 Razer Blade 15" (Mid 2019) - Base Model RZ09-03009 Razer Blade 15" Base - GTX1660 (2019)

Download the firmware updater here: http://rzr.to/lxOCn

For Model Numbers with prefixes:

RZ09-03017 Razer Blade 15" (Mid 2019) - Advanced Model RZ09-03018 Razer Blade 15" (Mid 2019) - Advanced Model

Download the firmware updater here: http://rzr.to/nRGKB

For Model Numbers with prefixes:

RZ09-02876 Razer Blade Pro 17" (2019) RZ09-02877 Razer Blade Pro 17" (2019) RZ09-02878 Razer Blade Pro 17" (2019)

Download the firmware updater here: http://rzr.to/DkqNg

For Model Numbers with prefixes:

RZ09-02385 Razer Blade 15 (2018) - Advanced Model RZ09-02386 Razer Blade 15 (2018) - Advanced Model

Download the firmware updater here: http://rzr.to/SjGBU

For Model Numbers with prefixes:

RZ09-02886 Razer Blade 15" (Early 2019) - Advanced Model RZ09-02887 Razer Blade 15" (Early 2019) - Advanced Model RZ09-02888 Razer Blade 15" (Early 2019) - Advanced Model

Download the firmware updater here: http://rzr.to/dwTWh

For Model Numbers with prefixes:

RZ09-02705 Razer Blade 15" (2018) - Base Model

Download the firmware updater here: http://rzr.to/gwEjF


For Model Numbers with prefixes:

RZ09-01682	Razer Blade Stealth 12.5" (2016) - Intel 6500U
RZ09-01962	Razer Blade Stealth 12.5" (2016) - Intel 7500U
RZ09-01963	Razer Blade Stealth 13" (2017) - Intel 7500U
RZ09-01964	Razer Blade Stealth 13" (2017) - Intel 7500U
RZ09-02393	Razer Blade Stealth 13" (2017) - Intel 8550U
RZ09-02394	Razer Blade Stealth 13" (2017) - Intel 8550U
RZ09-01652	Razer Blade 14" (2016) - GTX970M
RZ09-01952	Razer Blade 14" (2016) - Intel 6700HQ - GTX1060
RZ09-01953	Razer Blade 14" (2017) - Intel 7700HQ - GTX1060
RZ09-01662	Razer Blade Pro 17" (2016)
RZ09-01663	Razer Blade Pro 17" (2017)
RZ09-02202	Razer Blade Pro 17" (2017) – Full HD – GTX 1060

Download the firmware updater here: http://rzr.to/tPlWq


INSTALLATION PROCESS

1. Click on the updater file located in your chosen download location to begin the update process.



- 2. The User Account Control window may pop up to confirm changes that will be made by the application. Click "Yes" to allow the Razer Updater application to launch.
- 3. The Blade Updater window will appear with details regarding your current update version and the version your Razer Blade laptop will be updated too.

4. Click "UPDATE" to initiate the update process of your Razer Blade laptop. You may lose control of your mouse and keyboard during the updating process. You will also not be able to proceed if you already have the latest software installed.



- 5. A progress bar will appear indicating the status and progression of the installation process. During the install process, you will not have access to other applications. This update may take 15 minutes or longer to complete. Do not interrupt the installation process.
- 6. Once the progress bar reaches 100% completion, your Razer Blade will restart automatically. No further action or steps are required after the progress bar reaches 100%. Once your Blade has restarted your system will be updated.